



Figure 23. Historic aerial photographs (1/9/94 – 9/18/01) depicting shoreline change along the Dudley Island shoreline and marsh complex. Dotted arrow delineates axis of the main ebb channel (A-D). Note the encroachment of the ebb channel upon the marsh shoreline and the shift of the ebb channel resulting in the erosion of the eastern portion of the flood delta (A and B). Also note the spit shape changes that impact the ebb channel position and the erosion of Dudley Island. Rectangular shaped box delineates Island 1 and 2. Compare to Figures 23 and 24.