




US Army Corps
of Engineers
Wilmington District

EXHIBIT 16: BOUNDARY LINE MARKINGS W.KERR SCOTT DAM AND RESERVOIR

Witness trees in Wilmington District are painted orange to delineate the boundary line. Where trees are not available, a similarly marked metal or fiberglass post is used. A survey by a licensed surveyor will be necessary to determine the exact line location. The types and meanings of the markings are illustrated below.




COMPLETE CIRCLE
BANDS

FRONT

SIDE


WITNESS TREE FOR CORNER

Three bands are painted completely around tree with hack marks in the band facing the corner. A blaze is located approximately waist high facing the corner.




IN LINE TREE

Two bands each are painted on opposite sides of the tree in the direction of the line, with a hack cut in each band. The bands do not completely encircle the tree. A blaze is made above the bands. These markings indicate that the boundary line passes through the tree.




FRONT



SIDE

LINE WITNESS TREE

Two bands are painted on the tree with hacks facing in the direction of the line. The bands are painted around the edges of the tree, so that they may be seen from a distance when walking the line. These trees are normally on government property. Note that these trees are not the boundary line; they only illustrate on which side the boundary line falls.



FRONT

SIDE

